

KITCHEN  
STUFF  
METALLA  
DIGITAL KITCHEN SCALE

USER'S MANUAL

STK # 95283

---

*\* Please note that diagrams may vary based on different models*

Thank you for choosing our KSP Metalla Digital Kitchen Scale. To ensure proper operation and to maintain the lifespan and the utmost accuracy of the scale, please read this manual carefully before use.

## KEY FEATURES

- High precision strain gauge sensors system
- Stainless steel platform
- Min 3 g - Max 15 kg
- LCD display(back light optional)
- Units of measure are g/kg/oz/lb:oz/fl.oz
- Auto on & auto off
- Timer and clock function
- Low battery and over load indicator
- Easily switch within different units: kg/g/lb/oz/fl.oz.
- Requires 2x AAA (not included)


## BUTTONS



- **SET/UNIT** : Unit exchange / the timer mode
- **ON/ZERO** : Power on/off and set up the timer

## OPERATION

- Open the cover at the back of the scale, install the the 2x AAA batteries into the holder as picture show and cover it back.



- When the batteries are installed the LCD screen shows the time. (To setup the time please see the “Time Setting” on the next page)



- To enter the weighing mode press the “ON/ZERO” button and the LCD screen shows “0”. To change the unit press the “SET/UNIT” button.



## TIMER FUNCTION

1. Press the “SET/UNIT” button to enter the timer mode. In the weighing mode, press and hold the “SET/UNIT” button for 2 seconds. 1 minute timer starts directly.



2. In the timer mode, press the “ON/ZERO” button to setup timer. To add a minute press the “SET/UNIT” button and to add a second press the “ON/ZERO” button.
3. In the timer mode, press “SET/UNIT” button to stop and press it again to restart. Press the “ON/ZERO” button to clear timer data.
4. Press and hold the “ON/ZERO” button to exit the timer mode.

## CLOCK SETTING

1. To set up hours press and hold the “SET/UNIT” button for 2 seconds. To increase hours keep pressing the “UNIT” button.
2. To set up minutes press the “ON/ZERO” button and to increase minutes keep pressing the “SET/UNIT” button.
3. To complete time setting press the “ON/ZERO” button.
4. To switch to 24 hours complete 11:00 pm and to switch to 11 hours complete 23:00.



## CAUTION

- Please change a new battery when “LO” appears on the screen which indicates that the battery is out of power.



- “EEEE” showed on the screen indicates overload.



## ATTENTION

1. Please put the KSP Metalla Digital Kitchen Scale on hard and flat surface and make sure it is steady before use.
2. The maximum capacity of the KSP Metalla Digital Kitchen Scale is 15kg, which is the weight before using the tare function.
3. To clean use soft tissue with alcohol or glass cleaner. No soap or other chemicals. Keep it away from water, corrosive liquid, heat and extreme coldness.
4. The KSP Metalla Digital Kitchen Scale is high precision measuring device. Never knock it heavily or try to disassemble it and please handle it carefully to avoid dropping or breaking during moving.
5. The KSP Metalla Digital Kitchen Scale is for family use only and not suitable for professional use.
6. If the KSP Metalla Digital Kitchen Scale malfunctions please check the battery and change if necessary.

